

STC Listing, Commander Aircraft

Commander 112

<u>SA00068SE</u>	Installation of fuel flow/pressure instruments. (W/TSIO-360-MB1)	Reissued	10/15/2002
<u>SA00165BO</u>	Installation of Avidyne Corporation Datalink Coupler, part number 700-00015-000 per Avidyne	Issued	02/20/2003
<u>SA00197AT</u>	Installation of Appalachian carbon steel brake discs that have melonite surface treatment.	Reissued	11/14/1994
<u>SA00215NY</u>	Installation of CAVU Model AM100 AVMIX engine fuel/air mixture setting system.	Amended	08/14/1995
<u>SA00402SE</u>	Installation of a remote spin-on oil filter adapter. (GC-1B w/Lycoming or Cont 360 engine	Amended	04/24/2000
<u>SA00432SE</u>	Installation of EGT 701 series fuel flow instrument.	Amended	04/19/2002
<u>SA00499SE</u>	Installation of a Hartzell HC-E3YR-1RF/F7392 propeller and C-3535-1(P) spinner.	Amended	02/02/2002
<u>SA00861SE</u>	Installation of J.P. Instruments (JPI) fuel flow indicating system in accordance with JPI	Issued	12/18/2000
<u>SA00865SE</u>	Installation of vortex generators on the wings, horizontal tail surfaces and vertical fin.	Issued	01/09/2001
<u>SA00954SE (2 OF 2)</u>	Installation of J.P. Instruments (JPI) Primary Temperature Indicating System in accordance with JPI	Amended	08/11/2003
<u>SA01105WI-D (2 OF 2)</u>	Installation of Bendix/King KMD 550/850 Multi-Functional Display System with optional traffic,	Issued	08/16/2002
<u>SA01157LA</u>	Installation of Electronics International Model FP-5 or FP-5L fuel flow/fuel pressure instrument as	Reissued	12/03/2001
<u>SA01229SE (1 OF 4)</u>	Installation of CNX80 GPS WAAS Navigator with integrated VHF Navigation and Communication radios.	Issued	06/27/2003
<u>SA01280CH</u>	Installation of Challenger Spin-On Oil Filters.(For Cessna 182 model, s/n 67042 and up) (For Cessna	Issued	08/29/2000
<u>SA02154AK</u>	Installation of the UPS Aviation Technologies, Inc, Apollo MX20 multi-function display, P/N	Reissued	10/14/2003
<u>SA02203AK (1 OF 3)</u>	Installation of FlightLogic Synthetic Vision Electronic Flight Information System (EFIS-SV).	Issued	03/26/2003
<u>SA02532AT</u>	Installation of subject Michelin tires on appropriate aircraft. For Michelin 5, 6, 8, and 10-inch	Issued	06/05/2002
<u>SA09195AC-D</u>	Installation of S-TEC System 55 Two Axis Automatic flight guidance system, Model ST-658, with	Amended	05/23/2001
<u>SA09258AC-D</u>	Installation of S-TEC System 20/30 Single and Two Axis Automatic Flight Guidance Systems, Model	Amended	11/16/1998
<u>SA09259AC-D</u>	Installation of S-TEC System 30 ALT Altitude Hold System, Model ST-714.	Amended	10/12/1998
<u>SA09470SC</u>	Installation of Starter Indicator light system.	Issued	06/18/2001
<u>SA09832SC</u>	Installation of S-TEC System 55 Two Axis Automatic Flight Guidance System, Model ST-658.	Issued	10/31/2000
<u>SA10126SC (1 OF 2)</u>	Installation of Aero Advantage ADV200 series vacuum pump per Aero Advantage Drawing Number ADVMSI	Amended	03/27/2003
<u>SA1229CE</u>	Installation of King KFC-200, 2 axis(3 optional) flight control system with KCS 55/55A compass and	Reissued	02/28/2000

<u>SA1245SO</u>	Installation of an adjustable trim tab on the left aileron.	Issued	06/29/1981
<u>SA1502SW</u>	Mitchell automatic flight system AK364 consisting of Century I autopilot with optional omni tracker.	Reissued	07/10/1984
<u>SA1503SW</u>	Mitchell automatic flight system AK 363 consisting of Century IIB autopilot with optional radio	Reissued	07/10/1984
<u>SA1504SW</u>	Mitchell automatic flight system AK362 consisting of Century III autopilot with optional command/	Reissued	07/10/1984
<u>SA1505SW</u>	Mitchell command/electric pitch trim system.	Reissued	07/10/1984
<u>SA157NE</u>	Installation of Graphic Engine Monitor System Model GEM-602 S/N 403 and GEM-603 S/N001126and	Amended	10/18/1996
<u>SA1728SW</u>	Cabin air scoop.	Amended	03/14/1983
<u>SA237GL</u>	Install edge landing lights.	Amended	10/20/1998
<u>SA243NW</u>	Installation of Lycoming IO-540 engine with 3-bladed Hoffman, 3-bladed Hartzell, or 2-bladed	Amended	11/01/1998
<u>SA2586NM</u>	Installation of J.P. Instruments temperature monitoring systems.	Amended	06/17/1999
<u>SA2622NM</u>	Installation of Precise Flight Pulselite Control Unit in landing/taxi system. (767-200 B17) (DHC-8	Amended	05/20/1993
<u>SA2677CE</u>	Installation of aileron and flap gap seals.	Amended	07/30/2003
<u>SA2683NM</u>	Installation of Precise Flight, Inc. stand-by vacuum system (SVS)	Amended	06/19/2001
<u>SA2844CE</u>	Installation of a plastic cap enclosure over the anti-collision strobe light system.	Issued	07/29/1992
<u>SA3001SO</u>	Installation of Appalachian Accessories, stainless steel brake discs, P/N 75-43.	Reissued	09/29/1995
<u>SA3120SW-D</u>	Mitchell automatic flight system AK572 consisting of Century I autopilot with optional omni tracker.	Reissued	06/05/1984
<u>SA3121SW-D</u>	Mitchell automatic flight system AK473 consisting of Century IIB autopilot with optional radio	Reissued	06/05/1984
<u>SA3122SW-D</u>	Mitchell automatic flight system AK574 consisting of Century III autopilot with optional radio and	Reissued	06/05/1984
<u>SA3123SW-D</u>	Mitchell command electric trim system model AK582.	Reissued	06/05/1984
<u>SA3155WE</u>	Installation of Pathfinder autopilot systems and/or pitch trim systems.	Reissued	09/30/1998
<u>SA3862NM</u>	Installation of Electronics International Primary TIT/EGT/CHT instruments, remote switches and	Amended	04/25/1988
<u>SA4005NM</u>	Installation of Precise Pulselite control unit in landing/taxi system. (HP Jetstream Model 3101 AND	Amended	06/04/2001
<u>SA4172NM</u>	Installation of Aviation Development oil filter.	Amended	09/01/1999
<u>SA4302NM</u>	Installation of Electronics Int'l digital automatic engine analyzer.	Amended	03/05/1993
<u>SA4531NM</u>	Replace 100 watt landing light with a 250 watt lamp.	Issued	05/30/1989
<u>SA5154SW-D</u>	S-TEC System 60 two axis automatic flight guidance system ST-143 with optional automatic electric	Amended	07/21/2000
<u>SA5155SW-D</u>	S-TEC yaw damper system ST-145.	Amended	07/23/1987
<u>SA5159NM</u>	Installation of chip detector system.	Amended	11/06/1992
<u>SA5167SW-D</u>	S-TEC System 60 pitch stabilizer system ST-144 with optional autotrim system.	Amended	09/08/2000
<u>SA5187SW-D</u>	S-TEC System 60 single axis automatic flight.	Issued	07/29/1983
<u>SA5202NM</u>	Installation of Avco-Lycoming engine model IO-360-C1D6 modified.	Amended	03/06/1998
<u>SA5283SW-D</u>	S-TEC System 40/50 single and two axis automatic flight guidance system ST-217-40/50.	Issued	03/09/1984

<u>SA563CH</u>	Authorizes installation of engines equipped w/Unison Limited Authority Spark Advance Regulator	Amended	09/24/1997
<u>SA5656NM</u>	Installation of burglar alarm system.	Amended	07/21/1993
<u>SA5757SW</u>	Installation of Alcor tru-flow/ fuel flow/totalizer system.	Amended	09/30/2002
<u>SA5924NM</u>	Installation of RPM instrument.	Amended	06/03/1994
<u>SA5925NM</u>	Installation of oil pressure/temperature instrument.	Amended	06/03/1994
<u>SA593CH</u>	Install Unison SlickSTART tm magneto booster system.	Amended	04/20/2000
<u>SA615EA</u>	Installation of Whelen anti- collision strobe light system, Models HD, HR or HS (-14 (14V) or -28	Amended	06/18/1999
<u>SA666NW</u>	Installation of Teflon control yoke bushings.	Amended	05/15/1996
<u>SA7063NM</u>	Installation of acrylic window liners.	Amended	01/20/1999
<u>SA7155SW-D</u>	Installation of S-TEC System 65 two axis automatic flight guidance system, Model ST-420.	Amended	04/09/1996
<u>SA71GL (1 OF 3)</u>	Installation of air filters per AML No. SA71GL latest FAA approved revision on single-engine	Reissued	06/20/2000
<u>SA71GL (2 OF 3)</u>	Installation of air filters per AML No. SA71GL dated April 17, 1995 or latest FAA approved	Reissued	06/20/2000
<u>SA771GL</u>	Install nose gear shimmey dampener, P/N 1001, to replace Gerdes P/N A135-8.	Amended	09/12/1997
<u>SA7801SW-D</u>	Installation of S-TEC manual electric trim system.	Issued	07/16/1991
<u>SA800EA</u>	Installation of Aviation White Anti-Collision Strobe Lights. Whelen Models A429, A430, A434, A450,	Amended	09/08/1999
<u>SA8431SW</u>	Installation of R15VON alternator control unit.	Amended	01/06/1994
<u>SA8521SW-D</u>	Installation of a Century Automatic Flight System, Model YK1044 consisting of a Century yaw damper.	Issued	03/31/2000
<u>SA8534SW-D</u>	Installation of a Century Automatic Flight System, Model AK1056.	Amended	03/13/2003
<u>SA8922SW</u>	Installation of replacement Ultimate Engine Oil Filter for Textron Lycoming and Teledyne	Issued	07/21/1994
<u>ST01085LA (2 OF 2)</u>	Installation of the VNS 1000 Voice Navigation System.	Amended	02/26/2001
<u>ST01700NY (1 OF 2)</u>	Installation of the following Aerospace Logic aircraft instruments: EGT-100 Exhaust Gas Temperature	Issued	07/08/2003
<u>ST02547AT (2 OF 2)</u>	Installation of a voice alert system.	Amended	05/13/2003

Commander 112 Series

<u>SA01157LA</u>	Installation of Electronics International Model FP-5 or FP-5L fuel flow/fuel pressure instrument as	Reissued	12/03/2001
<u>SA01224AT</u>	Installation of wheel hub cabs with valve stem access door.	Amended	04/17/98
<u>SA02532AT</u>	Installation of subject Michelin tires on appropriate aircraft. For Michelin 5, 6, 8, and 10-inch	Issued	06/05/2002
<u>SA09470SC</u>	Installation of Starter Indicator light system.	Issued	06/18/2001
<u>SA09832SC</u>	Installation of S-TEC System 55 Two Axis Automatic Flight Guidance System, Model ST-658.	Issued	10/31/2000
<u>SA1626NM</u>	Installation of Electronics Int'l Digital EGT/CHT Instruments and accessories. (201 Series)	Amended	05/09/93
<u>SA2190NM</u>	Installation of electronics International Digital EGT/CHT Intruments and Accessories.	Reissued	05/24/88
<u>SA2350NM</u>	Installation of Electronics International digital EGT/CHT instruments and accessories.	Amended	05/24/88
<u>SA2687NM</u>	Installation of Truboplus/ Electronics Int'l gauges and switches.	Reissued	02/24/92
<u>SA2693NM</u>	Installation of Electronics International digital volt/amp gauges and accessories.	Amended	01/26/88
<u>SA2900WE</u>	Installation of Pathfinder autopilots.	Reissued	09/30/98
<u>SA4005NM</u>	Installation of Precise Pulselite control unit in landing/taxi system. (HP Jetstream Model 3101 AND	Amended	06/04/2001

Commander 112B

<u>SA00068SE</u>	Installation of fuel flow/pressure instruments. (W/TSIO-360-MB1)	Reissued	10/15/2002
<u>SA00192AT</u>	Installation of carbon steel brake discs that have melonite surface treatment.	Reissued	11/14/1994
<u>SA00197AT</u>	Installation of Appalachian carbon steel brake discs that have melonite surface treatment.	Reissued	11/14/1994
<u>SA00215NY</u>	Installation of CAVU Model AM100 AVMIX engine fuel/air mixture setting system.	Amended	08/14/1995
<u>SA00402SE</u>	Installation of a remote spin-on oil filter adapter. (GC-1B w/Lycoming or Cont 360 engine	Amended	04/24/2000
<u>SA00432SE</u>	Installation of EGT 701 series fuel flow instrument.	Amended	04/19/2002
<u>SA00499SE</u>	Installation of a Hartzell HC-E3YR-1RF/F7392 propeller and C-3535-1(P) spinner.	Amended	02/02/2002
<u>SA00861SE</u>	Installation of J.P. Instruments (JPI) fuel flow indicating system in accordance with JPI	Issued	12/18/2000
<u>SA00954SE (2 OF 2)</u>	Installation of J.P. Instruments (JPI) Primary Temperature Indicating System Amended in accordance with JPI	Amended	08/11/2003
<u>SA01105WI-D (2 OF 2)</u>	Installation of Bendix/King KMD 550/850 Multi-Functional Display System Issued with optional traffic,	Issued	08/16/2002
<u>SA01157LA</u>	Installation of Electronics International Model FP-5 or FP-5L fuel flow/fuel pressure instrument as	Reissued	12/03/2001
<u>SA01229SE (1 OF 4)</u>	Installation of CNX80 GPS WAAS Navigator with integrated VHF Navigation and Communication radios.	Issued	06/27/2003
<u>SA02154AK</u>	Installation of the UPS Aviation Technologies, Inc, Apollo MX20 multi-function display, P/N	Reissued	10/14/2003
<u>SA02203AK (1 OF 3)</u>	Installation of FlightLogic Synthetic Vision Electronic Flight Information System (EFIS-SV).	Issued	03/26/2003
<u>SA02532AT</u>	Installation of subject Michelin tires on appropriate aircraft. For Michelin 5, 6, 8, and 10-inch	Issued	06/05/2002
<u>SA09195AC-D</u>	Installation of S-TEC System 55 Two Axis Automatic flight guidance system, Model ST-658, with	Amended	05/23/2001
<u>SA09258AC-D</u>	Installation of S-TEC System 20/30 Single and Two Axis Automatic Flight Guidance Systems, Model	Amended	11/16/1998
<u>SA09259AC-D</u>	Installation of S-TEC System 30 ALT Altitude Hold System, Model ST-714.	Amended	10/12/1998
<u>SA09470SC</u>	Installation of Starter Indicator light system.	Issued	06/18/2001
<u>SA09832SC</u>	Installation of S-TEC System 55 Two Axis Automatic Flight Guidance System, Model ST-658.	Issued	10/31/2000
<u>SA10126SC (1 OF 2)</u>	Installation of Aero Advantage ADV200 series vacuum pump per Aero Advantage Drawing Number ADVMSI	Amended	03/27/2003
<u>SA1229CE</u>	Installation of King KFC-200, 2 axis(3 optional) flight control system with KCS 55/55A compass and	Reissued	02/28/2000
<u>SA1245SO</u>	Installation of an adjustable trim tab on the left aileron.	Issued	06/29/1981
<u>SA237GL</u>	Install edge landing lights.	Amended	10/20/1998
<u>SA2622NM</u>	Installation of Precise Flight Pulselite Control Unit in landing/taxi system. (767-200 B17) (DHC-8	Amended	05/20/1993
<u>SA2677CE</u>	Installation of aileron and flap gap seals.	Amended	07/30/2003
<u>SA2683NM</u>	Installation of Precise Flight, Inc. stand-by vacuum system (SVS)	Amended	06/19/2001
<u>SA3000SO</u>	Installation of Appalachian stainless steel brake discs, No. 75-15A.	Reissued	09/29/1995
<u>SA3001SO</u>	Installation of Appalachian Accessories, stainless steel brake discs, P/N 75-	Reissued	09/29/1995

43.

<u>SA3120SW-D</u>	Mitchell automatic flight system AK572 consisting of Century I autopilot with optional omni tracker.	Reissued	06/05/1984
<u>SA3121SW-D</u>	Mitchell automatic flight system AK473 consisting of Century IIB autopilot with optional radio	Reissued	06/05/1984
<u>SA3122SW-D</u>	Mitchell automatic flight system AK574 consisting of Century III autopilot with optional radio and	Reissued	06/05/1984
<u>SA3123SW-D</u>	Mitchell command electric trim system model AK582.	Reissued	06/05/1984
<u>SA3778WE</u>	Installation of retractable landing lights.	Issued	11/08/1978
<u>SA4005NM</u>	Installation of Precise Pulselite control unit in landing/taxi system. (HP Jetstream Model 3101 AND	Amended	06/04/2001
<u>SA4172NM</u>	Installation of Aviation Development oil filter.	Amended	09/01/1999
<u>SA5154SW-D</u>	S-TEC System 60 two axis automatic flight guidance system ST-143 with optional automatic electric	Amended	07/21/2000
<u>SA5155SW-D</u>	S-TEC yaw damper system ST-145.	Amended	07/23/1987
<u>SA5167SW-D</u>	S-TEC System 60 pitch stabilizer system ST-144 with optional autotrim system.	Amended	09/08/2000
<u>SA5187SW-D</u>	S-TEC System 60 single axis automatic flight.	Issued	07/29/1983
<u>SA5202NM</u>	Installation of Avco-Lycoming engine model IO-360-C1D6 modified.	Amended	03/06/1998
<u>SA5283SW-D</u>	S-TEC System 40/50 single and two axis automatic flight guidance system ST-217-40/50.	Issued	03/09/1984
<u>SA563CH</u>	Authorizes installation of engines equipped w/Unison Limited Authority Spark Advance Regulator	Amended	09/24/1997
<u>SA5757SW</u>	Installation of Alcor tru-flow/ fuel flow/totalizer system.	Amended	09/30/2002
<u>SA5924NM</u>	Installation of RPM instrument.	Amended	06/03/1994
<u>SA5925NM</u>	Installation of oil pressure/temperature instrument.	Amended	06/03/1994
<u>SA593CH</u>	Install Unison SlickSTART tm magneto booster system.	Amended	04/20/2000
<u>SA7063NM</u>	Installation of acrylic window liners.	Amended	01/20/1999
<u>SA7155SW-D</u>	Installation of S-TEC System 65 two axis automatic flight guidance system, Model ST-420.	Amended	04/09/1996
<u>SA71GL (1 OF 3)</u>	Installation of air filters per AML No. SA71GL latest FAA approved revision on single-engine	Reissued	06/20/2000
<u>SA71GL (2 OF 3)</u>	Installation of air filters per AML No. SA71GL dated April 17, 1995 or latest FAA approved	Reissued	06/20/2000
<u>SA771GL</u>	Install nose gear shimmey dampener, P/N 1001, to replace Gerdes P/N A135-8.	Amended	09/12/1997
<u>SA7801SW-D</u>	Installation of S-TEC manual electric trim system.	Issued	07/16/1991
<u>SA8431SW</u>	Installation of R15VON alternator control unit.	Amended	01/06/1994
<u>SA8521SW-D</u>	Installation of a Century Automatic Flight System, Model YK1044 consisting of a Century yaw damper.	Issued	03/31/2000
<u>SA8534SW-D</u>	Installation of a Century Automatic Flight System, Model AK1056.	Amended	03/13/2003
<u>ST01085LA (2 OF 2)</u>	Installation of the VNS 1000 Voice Navigation System.	Amended	02/26/2001
<u>ST01700NY (1 OF 2)</u>	Installation of the following Aerospace Logic aircraft instruments: EGT-100 Exhaust Gas Temperature	Issued	07/08/2003
<u>ST02547AT (2 OF 2)</u>	Installation of a voice alert system.	Amended	05/13/2003

Commander 112TC

<u>SA00068SE</u>	Installation of fuel flow/pressure instruments. (W/TSIO-360-MB1)	Reissued	10/15/2002
<u>SA00192AT</u>	Installation of carbon steel brake discs that have melonite surface treatment.	Reissued	11/14/1994
<u>SA00402SE</u>	Installation of a remote spin-on oil filter adapter. (GC-1B w/Lycoming or Cont 360 engine	Amended	04/24/2000
<u>SA00432SE</u>	Installation of EGT 701 series fuel flow instrument.	Amended	04/19/2002
<u>SA00499SE</u>	Installation of a Hartzell HC-E3YR-1RF/F7392 propeller and C-3535-1(P) spinner.	Amended	02/02/2002
<u>SA00861SE</u>	Installation of J.P. Instruments (JPI) fuel flow indicating system in accordance with JPI	Issued	12/18/2000
<u>SA00865SE</u>	Installation of vortex generators on the wings, horizontal tail surfaces and vertical fin.	Issued	01/09/2001
<u>SA00954SE (2 OF 2)</u>	Installation of J.P. Instruments (JPI) Primary Temperature Indicating System in accordance with JPI	Amended	08/11/2003
<u>SA01105WI-D (2 OF 2)</u>	Installation of Bendix/King KMD 550/850 Multi-Functional Display System with optional traffic,	Issued	08/16/2002
<u>SA01157LA</u>	Installation of Electronics International Model FP-5 or FP-5L fuel flow/fuel pressure instrument as	Reissued	12/03/2001
<u>SA01229SE (1 OF 4)</u>	Installation of CNX80 GPS WAAS Navigator with integrated VHF Navigation and Communication radios.	Issued	06/27/2003
<u>SA01280CH</u>	Installation of Challenger Spin-On Oil Filters.(For Cessna 182 model, s/n 67042 and up) (For Cessna	Issued	08/29/2000
<u>SA02154AK</u>	Installation of the UPS Aviation Technologies, Inc, Apollo MX20 multi-function display, P/N	Reissued	10/14/2003
<u>SA02203AK (1 OF 3)</u>	Installation of FlightLogic Synthetic Vision Electronic Flight Information System (EFIS-SV).	Issued	03/26/2003
<u>SA02532AT</u>	Installation of subject Michelin tires on appropriate aircraft. For Michelin 5, 6, 8, and 10-inch	Issued	06/05/2002
<u>SA09195AC-D</u>	Installation of S-TEC System 55 Two Axis Automatic flight guidance system, Model ST-658, with	Amended	05/23/2001
<u>SA09258AC-D</u>	Installation of S-TEC System 20/30 Single and Two Axis Automatic Flight Guidance Systems, Model	Amended	11/16/1998
<u>SA09259AC-D</u>	Installation of S-TEC System 30 ALT Altitude Hold System, Model ST-714.	Amended	10/12/1998
<u>SA09470SC</u>	Installation of Starter Indicator light system.	Issued	06/18/2001
<u>SA09832SC</u>	Installation of S-TEC System 55 Two Axis Automatic Flight Guidance System, Model ST-658.	Issued	10/31/2000
<u>SA10126SC (1 OF 2)</u>	Installation of Aero Advantage ADV200 series vacuum pump per Aero Advantage Drawing Number ADVMSI	Amended	03/27/2003
<u>SA1229CE</u>	Installation of King KFC-200, 2 axis(3 optional) flight control system with KCS 55/55A compass and	Reissued	02/28/2000
<u>SA1245SO</u>	Installation of an adjustable trim tab on the left aileron.	Issued	06/29/1981
<u>SA1418SO</u>	Replacement of rotor vanes in Airborne 211CC and 212CW vacuum pumps. (See limitations)	Reissued	06/12/1984
<u>SA237GL</u>	Install edge landing lights.	Amended	10/20/1998
<u>SA2622NM</u>	Installation of Precise Flight Pulselite Control Unit in landing/taxi system. (767-200 B17) (DHC-8	Amended	05/20/1993
<u>SA2677CE</u>	Installation of aileron and flap gap seals.	Amended	07/30/2003
<u>SA2683NM</u>	Installation of Precise Flight, Inc. stand-by vacuum system (SVS)	Amended	06/19/2001

<u>SA3000SO</u>	Installation of Appalachian stainless steel brake discs, No. 75-15A.	Reissued	09/29/1995
<u>SA300CE</u>	Installation of Woodward propeller governors on single and twin engine aircraft. (PA-31-325	Amended	05/14/1992
<u>SA3120SW-D</u>	Mitchell automatic flight system AK572 consisting of Century I autopilot with optional omni tracker.	Reissued	06/05/1984
<u>SA3121SW-D</u>	Mitchell automatic flight system AK473 consisting of Century IIB autopilot with optional radio	Reissued	06/05/1984
<u>SA3122SW-D</u>	Mitchell automatic flight system AK574 consisting of Century III autopilot with optional radio and	Reissued	06/05/1984
<u>SA3123SW-D</u>	Mitchell command electric trim system model AK582.	Reissued	06/05/1984
<u>SA3778WE</u>	Installation of retractable landing lights.	Issued	11/08/1978
<u>SA3787WE</u>	Installation of Model CFS-1000, -1001, FT-100, or FT-101 fuel flow indicating system.	Reissued	01/30/1998
<u>SA3920WE</u>	Installation of Fueltron IG or IP or Fuelgard digital fuel flow and totalizer system.	Reissued	04/29/1991
<u>SA4005NM</u>	Installation of Precise Pulselite control unit in landing/taxi system. (HP Jetstream Model 3101 AND	Amended	06/04/2001
<u>SA4172NM</u>	Installation of Aviation Development oil filter.	Amended	09/01/1999
<u>SA4479NM</u>	Installation of FC/FT-10 digital fuel flow indicating system.	Issued	06/20/1988
<u>SA5154SW-D</u>	S-TEC System 60 two axis automatic flight guidance system ST-143 with optional automatic electric	Amended	07/21/2000
<u>SA5167SW-D</u>	S-TEC System 60 pitch stabilizer system ST-144 with optional autotrim system.	Amended	09/08/2000
<u>SA5757SW</u>	Installation of Alcor tru-flow/ fuel flow/totalizer system.	Amended	09/30/2002
<u>SA5924NM</u>	Installation of RPM instrument.	Amended	06/03/1994
<u>SA5925NM</u>	Installation of oil pressure/temperature instrument.	Amended	06/03/1994
<u>SA7063NM</u>	Installation of acrylic window liners.	Amended	01/20/1999
<u>SA7155SW-D</u>	Installation of S-TEC System 65 two axis automatic flight guidance system, Model ST-420.	Amended	04/09/1996
<u>SA71GL (1 OF 3)</u>	Installation of air filters per AML No. SA71GL latest FAA approved revision on single-engine	Reissued	06/20/2000
<u>SA71GL (2 OF 3)</u>	Installation of air filters per AML No. SA71GL dated April 17, 1995 or latest FAA approved	Reissued	06/20/2000
<u>SA771GL</u>	Install nose gear shimmey dampener, P/N 1001, to replace Gerdes P/N A135-8.	Amended	09/12/1997
<u>SA8431SW</u>	Installation of R15VON alternator control unit.	Amended	01/06/1994
<u>SA8534SW-D</u>	Installation of a Century Automatic Flight System, Model AK1056.	Amended	03/13/2003
<u>SA8922SW</u>	Installation of replacement Ultimate Engine Oil Filter for Textron Lycoming and Teledyne	Issued	07/21/1994
<u>ST01085LA (2 OF 2)</u>	Installation of the VNS 1000 Voice Navigation System.	Amended	02/26/2001
<u>ST01700NY (1 OF 2)</u>	Installation of the following Aerospace Logic aircraft instruments: EGT-100 Exhaust Gas Temperature	Issued	07/08/2003
<u>ST02547AT (2 OF 2)</u>	Installation of a voice alert system.	Amended	05/13/2003

Commander 112TCA

<u>SA00068SE</u>	Installation of fuel flow/pressure instruments. (W/TSIO-360-MB1)	Reissued	10/15/2002
<u>SA00192AT</u>	Installation of carbon steel brake discs that have melonite surface treatment.	Reissued	11/14/94
<u>SA00402SE</u>	Installation of a remote spin-on oil filter adapter. (GC-1B w/Lycoming or Cont 360 engine	Amended	04/24/2000
<u>SA00432SE</u>	Installation of EGT 701 series fuel flow instrument.	Amended	04/19/2002
<u>SA00499SE</u>	Installation of a Hartzell HC-E3YR-1RF/F7392 propeller and C-3535-1(P) spinner.	Amended	02/02/2002
<u>SA00861SE</u>	Installation of J.P. Instruments (JPI) fuel flow indicating system in accordance with JPI	Issued	12/18/2000
<u>SA00865SE</u>	Installation of vortex generators on the wings, horizontal tail surfaces and vertical fin.	Issued	01/09/2001
<u>SA00954SE (2 OF 2)</u>	Installation of J.P. Instruments (JPI) Primary Temperature Indicating System in accordance with JPI	Amended	08/11/2003
<u>SA01105WI-D (2 OF 2)</u>	Installation of Bendix/King KMD 550/850 Multi-Functional Display System with optional traffic,	Issued	08/16/2002
<u>SA01157LA</u>	Installation of Electronics International Model FP-5 or FP-5L fuel flow/fuel pressure instrument as	Reissued	12/03/2001
<u>SA01229SE (1 OF 4)</u>	Installation of CNX80 GPS WAAS Navigator with integrated VHF Navigation and Communication radios.	Issued	06/27/2003
<u>SA02154AK</u>	Installation of the UPS Aviation Technologies, Inc, Apollo MX20 multi-function display, P/N	Reissued	10/14/2003
<u>SA02203AK (1 OF 3)</u>	Installation of FlightLogic Synthetic Vision Electronic Flight Information System (EFIS-SV).	Issued	03/26/2003
<u>SA02532AT</u>	Installation of subject Michelin tires on appropriate aircraft. For Michelin 5, 6, 8, and 10-inch	Issued	06/05/2002
<u>SA09195AC-D</u>	Installation of S-TEC System 55 Two Axis Automatic flight guidance system, Model ST-658, with	Amended	05/23/2001
<u>SA09258AC-D</u>	Installation of S-TEC System 20/30 Single and Two Axis Automatic Flight Guidance Systems, Model	Amended	11/16/98
<u>SA09259AC-D</u>	Installation of S-TEC System 30 ALT Altitude Hold System, Model ST-714.	Amended	10/12/98
<u>SA09470SC</u>	Installation of Starter Indicator light system.	Issued	06/18/2001
<u>SA09832SC</u>	Installation of S-TEC System 55 Two Axis Automatic Flight Guidance System, Model ST-658.	Issued	10/31/2000
<u>SA1229CE</u>	Installation of King KFC-200, 2 axis(3 optional) flight control system with KCS 55/55A compass and	Reissued	02/28/2000
<u>SA1245SO</u>	Installation of an adjustable trim tab on the left aileron.	Issued	06/29/81
<u>SA1418SO</u>	Replacement of rotor vanes in Airborne 211CC and 212CW vacuum pumps. (See limitations)	Reissued	06/12/84
<u>SA237GL</u>	Install edge landing lights.	Amended	10/20/98
<u>SA2622NM</u>	Installation of Precise Flight Pulselite Control Unit in landing/taxi system. (767-200 B17) (DHC-8	Amended	05/20/93
<u>SA2677CE</u>	Installation of aileron and flap gap seals.	Amended	07/30/2003
<u>SA2683NM</u>	Installation of Precise Flight, Inc. stand-by vacuum system (SVS)	Amended	06/19/2001
<u>SA3000SO</u>	Installation of Appalachian stainless steel brake discs, No. 75-15A.	Reissued	09/29/95
<u>SA300CE</u>	Installation of Woodward propeller governors on single and twin engine aircraft. (PA-31-325	Amended	05/14/92

<u>SA3120SW-D</u>	Mitchell automatic flight system AK572 consisting of Century I autopilot with optional omni tracker.	Reissued	06/05/84
<u>SA3121SW-D</u>	Mitchell automatic flight system AK473 consisting of Century IIB autopilot with optional radio	Reissued	06/05/84
<u>SA3122SW-D</u>	Mitchell automatic flight system AK574 consisting of Century III autopilot with optional radio and	Reissued	06/05/84
<u>SA3123SW-D</u>	Mitchell command electric trim system model AK582.	Reissued	06/05/84
<u>SA3778WE</u>	Installation of retractable landing lights.	Issued	11/08/78
<u>SA3787WE</u>	Installation of Model CFS-1000, -1001, FT-100, or FT-101 fuel flow indicating system.	Reissued	01/30/98
<u>SA3920WE</u>	Installation of Fueltron IG or IP or Fuelgard digital fuel flow and totalizer system.	Reissued	04/29/91
<u>SA4005NM</u>	Installation of Precise Pulselite control unit in landing/taxi system. (HP Jetstream Model 3101 AND	Amended	06/04/2001
<u>SA4172NM</u>	Installation of Aviation Development oil filter.	Amended	09/01/99
<u>SA4479NM</u>	Installation of FC/FT-10 digital fuel flow indicating system.	Issued	06/20/88
<u>SA5154SW-D</u>	S-TEC System 60 two axis automatic flight guidance system ST-143 with optional automatic electric	Amended	07/21/2000
<u>SA5167SW-D</u>	S-TEC System 60 pitch stabilizer system ST-144 with optional autotrim system.	Amended	09/08/2000
<u>SA5757SW</u>	Installation of Alcor tru-flow/ fuel flow/totalizer system.	Amended	09/30/2002
<u>SA5924NM</u>	Installation of RPM instrument.	Amended	06/03/94
<u>SA5925NM</u>	Installation of oil pressure/temperature instrument.	Amended	06/03/94
<u>SA7063NM</u>	Installation of acrylic window liners.	Amended	01/20/99
<u>SA7155SW-D</u>	Installation of S-TEC System 65 two axis automatic flight guidance system, Model ST-420.	Amended	04/09/96
<u>SA71GL (1 OF 3)</u>	Installation of air filters per AML No. SA71GL latest FAA approved revision on single-engine	Reissued	06/20/2000
<u>SA71GL (2 OF 3)</u>	Installation of air filters per AML No. SA71GL dated April 17, 1995 or latest FAA approved	Reissued	06/20/2000
<u>SA771GL</u>	Install nose gear shimmey dampener, P/N 1001, to replace Gerdes P/N A135-8.	Amended	09/12/97
<u>SA8431SW</u>	Installation of R15VON alternator control unit.	Amended	01/06/94
<u>SA8922SW</u>	Installation of replacement Ultimate Engine Oil Filter for Textron Lycoming and Teledyne	Issued	07/21/94
<u>ST01085LA (2 OF 2)</u>	Installation of the VNS 1000 Voice Navigation System.	Amended	02/26/2001
<u>ST01700NY (1 OF 2)</u>	Installation of the following Aerospace Logic aircraft instruments: EGT-100 Exhaust Gas Temperature	Issued	07/08/2003
<u>ST02547AT (2 OF 2)</u>	Installation of a voice alert system.	Amended	05/13/2003

Commander 114

<u>SA00068SE</u>	Installation of fuel flow/pressure instruments. (W/TSIO-360-MB1)	Reissued	10/15/2002
<u>SA00165BO</u>	Installation of Avidyne Corporation Datalink Coupler, part number 700-00015-000 per Avidyne	Issued	02/20/2003
<u>SA00192AT</u>	Installation of carbon steel brake discs that have melonite surface treatment.	Reissued	11/14/1994
<u>SA00215NY</u>	Installation of CAVU Model AM100 AVMIX engine fuel/air mixture setting system.	Amended	08/14/1995
<u>SA00356DE</u>	Installation of modified Textron Lycoming engine equipped with turbo normalizing system.	Amended	03/14/2000
<u>SA00402SE</u>	Installation of a remote spin-on oil filter adapter. (GC-1B w/Lycoming or Cont 360 engine	Amended	04/24/2000
<u>SA00432SE</u>	Installation of EGT 701 series fuel flow instrument.	Amended	04/19/2002
<u>SA00861SE</u>	Installation of J.P. Instruments (JPI) fuel flow indicating system in accordance with JPI	Issued	12/18/2000
<u>SA00865SE</u>	Installation of vortex generators on the wings, horizontal tail surfaces and vertical fin.	Issued	01/09/2001
<u>SA00954SE (2 OF 2)</u>	Installation of J.P. Instruments (JPI) Primary Temperature Indicating System in accordance with JPI	Amended	08/11/2003
<u>SA01105WI-D (2 OF 2)</u>	Installation of Bendix/King KMD 550/850 Multi-Functional Display System with optional traffic,	Issued	08/16/2002
<u>SA01157LA</u>	Installation of Electronics International Model FP-5 or FP-5L fuel flow/fuel pressure instrument as	Reissued	12/03/2001
<u>SA01229SE (1 OF 4)</u>	Installation of CNX80 GPS WAAS Navigator with integrated VHF Navigation and Communication radios.	Issued	06/27/2003
<u>SA01280CH</u>	Installation of Challenger Spin-On Oil Filters.(For Cessna 182 model, s/n 67042 and up) (For Cessna	Issued	08/29/2000
<u>SA02154AK</u>	Installation of the UPS Aviation Technologies, Inc, Apollo MX20 multi-function display, P/N	Reissued	10/14/2003
<u>SA02203AK (1 OF 3)</u>	Installation of FlightLogic Synthetic Vision Electronic Flight Information System (EFIS-SV).	Issued	03/26/2003
<u>SA02532AT</u>	Installation of subject Michelin tires on appropriate aircraft. For Michelin 5, 6, 8, and 10-inch	Issued	06/05/2002
<u>SA09195AC-D</u>	Installation of S-TEC System 55 Two Axis Automatic flight guidance system, Model ST-658, with	Amended	05/23/2001
<u>SA09258AC-D</u>	Installation of S-TEC System 20/30 Single and Two Axis Automatic Flight Guidance Systems, Model	Amended	11/16/1998
<u>SA09259AC-D</u>	Installation of S-TEC System 30 ALT Altitude Hold System, Model ST-714.	Amended	10/12/1998
<u>SA09470SC</u>	Installation of Starter Indicator light system.	Issued	06/18/2001
<u>SA09832SC</u>	Installation of S-TEC System 55 Two Axis Automatic Flight Guidance System, Model ST-658.	Issued	10/31/2000
<u>SA10126SC (1 OF 2)</u>	Installation of Aero Advantage ADV200 series vacuum pump per Aero Advantage Drawing Number ADVMSI	Amended	03/27/2003
<u>SA1229CE</u>	Installation of King KFC-200, 2 axis(3 optional) flight control system with KCS 55/55A compass and	Reissued	02/28/2000
<u>SA1245SO</u>	Installation of an adjustable trim tab on the left aileron.	Issued	06/29/1981
<u>SA1418SO</u>	Replacement of rotor vanes in Airborne 211CC and 212CW vacuum pumps. (See limitations)	Reissued	06/12/1984
<u>SA157NE</u>	Installation of Graphic Engine Monitor System Model GEM-602 S/N 403 and GEM-603 S/N001126and	Amended	10/18/1996

<u>SA237GL</u>	Install edge landing lights.	Amended	10/20/1998
<u>SA2586NM</u>	Installation of J.P. Instruments temperature monitoring systems.	Amended	06/17/1999
<u>SA2622NM</u>	Installation of Precise Flight Pulselite Control Unit in landing/taxi system. (767-200 B17) (DHC-8)	Amended	05/20/1993
<u>SA2677CE</u>	Installation of aileron and flap gap seals.	Amended	07/30/2003
<u>SA2683NM</u>	Installation of Precise Flight, Inc. stand-by vacuum system (SVS)	Amended	06/19/2001
<u>SA3000SO</u>	Installation of Appalachian stainless steel brake discs, No. 75-15A.	Reissued	09/29/1995
<u>SA300CE</u>	Installation of Woodward propeller governors on single and twin engine aircraft. (PA-31-325)	Amended	05/14/1992
<u>SA3120SW-D</u>	Mitchell automatic flight system AK572 consisting of Century I autopilot with optional omni tracker.	Reissued	06/05/1984
<u>SA3121SW-D</u>	Mitchell automatic flight system AK473 consisting of Century IIB autopilot with optional radio	Reissued	06/05/1984
<u>SA3122SW-D</u>	Mitchell automatic flight system AK574 consisting of Century III autopilot with optional radio and	Reissued	06/05/1984
<u>SA3123SW-D</u>	Mitchell command electric trim system model AK582.	Reissued	06/05/1984
<u>SA3308WE</u>	Modification of aileron control system by addition of aileron centering spring and installation of	Reissued	09/30/1998
<u>SA3531NM</u>	Installing copper electrical cables. (182 S/N 33000 THRU 33842) (8E 833 and UP)	Amended	04/01/1999
<u>SA3727WE</u>	Installation of Model CFS-1000, -1001, FT-100, or FT-101 fuel flow indicating system.	Reissued	01/30/1998
<u>SA3778WE</u>	Installation of retractable landing lights.	Issued	11/08/1978
<u>SA4005NM</u>	Installation of Precise Pulselite control unit in landing/taxi system. (HP Jetstream Model 3101 AND	Amended	06/04/2001
<u>SA4172NM</u>	Installation of Aviation Development oil filter.	Amended	09/01/1999
<u>SA4444NM</u>	Installation of McCauley B3D34C405/90DFA-13 propeller.	Issued	07/09/1982
<u>SA4531NM</u>	Replace 100 watt landing light with a 250 watt lamp.	Issued	05/30/1989
<u>SA5154SW-D</u>	S-TEC System 60 two axis automatic flight guidance system ST-143 with optional automatic electric	Amended	07/21/2000
<u>SA5155SW-D</u>	S-TEC yaw damper system ST-145.	Amended	07/23/1987
<u>SA5167SW-D</u>	S-TEC System 60 pitch stabilizer system ST-144 with optional autotrim system.	Amended	09/08/2000
<u>SA5187SW-D</u>	S-TEC System 60 single axis automatic flight.	Issued	07/29/1983
<u>SA5283SW-D</u>	S-TEC System 40/50 single and two axis automatic flight guidance system ST-217-40/50.	Issued	03/09/1984
<u>SA5656NM</u>	Installation of burglar alarm system.	Amended	07/21/1993
<u>SA5924NM</u>	Installation of RPM instrument.	Amended	06/03/1994
<u>SA5925NM</u>	Installation of oil pressure/temperature instrument.	Amended	06/03/1994
<u>SA7063NM</u>	Installation of acrylic window liners.	Amended	01/20/1999
<u>SA7155SW-D</u>	Installation of S-TEC System 65 two axis automatic flight guidance system, Model ST-420.	Amended	04/09/1996
<u>SA71GL (1 OF 3)</u>	Installation of air filters per AML No. SA71GL latest FAA approved revision on single-engine	Reissued	06/20/2000
<u>SA71GL (2 OF 3)</u>	Installation of air filters per AML No. SA71GL dated April 17, 1995 or latest FAA approved	Reissued	06/20/2000
<u>SA771GL</u>	Install nose gear shimmey dampener, P/N 1001, to replace Gerdes P/N A135-8.	Amended	09/12/1997

<u>SA7801SW-D</u>	Installation of S-TEC manual electric trim system.	Issued	07/16/1991
<u>SA7855SW</u>	Installation of McCauley B3D32C419/82NHA-5 propeller.	Amended	09/10/1990
<u>SA8521SW-D</u>	Installation of a Century Automatic Flight System, Model YK1044 consisting of a Century yaw damper.	Issued	03/31/2000
<u>SA8534SW-D</u>	Installation of a Century Automatic Flight System, Model AK1056.	Amended	03/13/2003
<u>SA8922SW</u>	Installation of replacement Ultimate Engine Oil Filter for Textron Lycoming and Teledyne	Issued	07/21/1994
<u>ST01085LA (2 OF 2)</u>	Installation of the VNS 1000 Voice Navigation System.	Amended	02/26/2001
<u>ST01700NY (1 OF 2)</u>	Installation of the following Aerospace Logic aircraft instruments: EGT-100 Exhaust Gas Temperature	Issued	07/08/2003
<u>ST02547AT (2 OF 2)</u>	Installation of a voice alert system.	Amended	05/13/2003

Commander 114 Series

<u>SA00865SE</u>	Installation of vortex generators on the wings, horizontal tail surfaces and vertical fin.	Issued	01/09/2001
<u>SA01224AT</u>	Installation of wheel hub cabs with valve stem access door.	Amended	04/17/1998
<u>SA02532AT</u>	Installation of subject Michelin tires on appropriate aircraft. For Michelin 5, 6, 8, and 10-inch	Issued	06/05/2002
<u>SA09470SC</u>	Installation of Starter Indicator light system.	Issued	06/18/2001
<u>SA1626NM</u>	Installation of Electronics Int'l Digital EGT/CHT Instruments and accessories. (201 Series)	Amended	05/09/1993
<u>SA2693NM</u>	Installation of Electronics International digital volt/amp gauges and accessories.	Amended	01/26/1988
<u>SA3862NM</u>	Installation of Electronics International Primary TIT/EGT/CHT instruments, remote switches and	Amended	04/25/1988
<u>SA4302NM</u>	Installation of Electronics Int'l digital automatic engine analyzer.	Amended	03/05/1993
<u>SA5159NM</u>	Installation of chip detector system.	Amended	11/06/1992

Commander 114A

<u>SA00068SE</u>	Installation of fuel flow/pressure instruments. (W/TSIO-360-MB1)	Reissued	10/15/2002
<u>SA00215NY</u>	Installation of CAVU Model AM100 AVMIX engine fuel/air mixture setting system.	Amended	08/14/1995
<u>SA00356DE</u>	Installation of modified Textron Lycoming engine equipped with turbo normalizing system.	Amended	03/14/2000
<u>SA00402SE</u>	Installation of a remote spin-on oil filter adapter. (GC-1B w/Lycoming or Cont 360 engine	Amended	04/24/2000
<u>SA00432SE</u>	Installation of EGT 701 series fuel flow instrument.	Amended	04/19/2002
<u>SA00861SE</u>	Installation of J.P. Instruments (JPI) fuel flow indicating system in accordance with JPI	Issued	12/18/2000
<u>SA00865SE</u>	Installation of vortex generators on the wings, horizontal tail surfaces and vertical fin.	Issued	01/09/2001
<u>SA01105WI-D (2 OF 2)</u>	Installation of Bendix/King KMD 550/850 Multi-Functional Display System with optional traffic,	Issued	08/16/2002
<u>SA01157LA</u>	Installation of Electronics International Model FP-5 or FP-5L fuel flow/fuel pressure instrument as	Reissued	12/03/2001
<u>SA01229SE (1 OF 4)</u>	Installation of CNX80 GPS WAAS Navigator with integrated VHF Navigation and Communication radios.	Issued	06/27/2003
<u>SA02154AK</u>	Installation of the UPS Aviation Technologies, Inc, Apollo MX20 multi-function display, P/N	Reissued	10/14/2003
<u>SA02203AK (1 OF 3)</u>	Installation of FlightLogic Synthetic Vision Electronic Flight Information System (EFIS-SV).	Issued	03/26/2003
<u>SA02532AT</u>	Installation of subject Michelin tires on appropriate aircraft. For Michelin 5, 6, 8, and 10-inch	Issued	06/05/2002
<u>SA09195AC-D</u>	Installation of S-TEC System 55 Two Axis Automatic flight guidance system, Model ST-658, with	Amended	05/23/2001
<u>SA09258AC-D</u>	Installation of S-TEC System 20/30 Single and Two Axis Automatic Flight Guidance Systems, Model	Amended	11/16/1998
<u>SA09259AC-D</u>	Installation of S-TEC System 30 ALT Altitude Hold System, Model ST-714.	Amended	10/12/1998
<u>SA09470SC</u>	Installation of Starter Indicator light system.	Issued	06/18/2001
<u>SA09832SC</u>	Installation of S-TEC System 55 Two Axis Automatic Flight Guidance System, Model ST-658.	Issued	10/31/2000
<u>SA10126SC (1 OF 2)</u>	Installation of Aero Advantage ADV200 series vacuum pump per Aero Advantage Drawing Number ADVMSI	Amended	03/27/2003
<u>SA1245SQ</u>	Installation of an adjustable trim tab on the left aileron.	Issued	06/29/1981
<u>SA1389GL</u>	Installation of Pamco emergency backup pneumatic system. (114A S/N 14350 AND AFTER)	Issued	06/23/1989
<u>SA237GL</u>	Install edge landing lights.	Amended	10/20/1998
<u>SA2622NM</u>	Installation of Precise Flight Pulselite Control Unit in landing/taxi system. (767-200 B17) (DHC-8	Amended	05/20/1993
<u>SA2677CE</u>	Installation of aileron and flap gap seals.	Amended	07/30/2003
<u>SA2683NM</u>	Installation of Precise Flight, Inc. stand-by vacuum system (SVS)	Amended	06/19/2001
<u>SA3120SW-D</u>	Mitchell automatic flight system AK572 consisting of Century I autopilot with optional omni tracker.	Reissued	06/05/1984
<u>SA3121SW-D</u>	Mitchell automatic flight system AK473 consisting of Century IIB autopilot with optional radio	Reissued	06/05/1984
<u>SA3122SW-D</u>	Mitchell automatic flight system AK574 consisting of Century III autopilot with optional radio and	Reissued	06/05/1984

<u>SA3123SW-D</u>	Mitchell command electric trim system model AK582.	Reissued	06/05/1984
<u>SA4172NM</u>	Installation of Aviation Development oil filter.	Amended	09/01/1999
<u>SA5154SW-D</u>	S-TEC System 60 two axis automatic flight guidance system ST-143 with optional automatic electric	Amended	07/21/2000
<u>SA5155SW-D</u>	S-TEC yaw damper system ST-145.	Amended	07/23/1987
<u>SA5167SW-D</u>	S-TEC System 60 pitch stabilizer system ST-144 with optional autotrim system.	Amended	09/08/2000
<u>SA5187SW-D</u>	S-TEC System 60 single axis automatic flight.	Issued	07/29/1983
<u>SA5283SW-D</u>	S-TEC System 40/50 single and two axis automatic flight guidance system ST-217-40/50.	Issued	03/09/1984
<u>SA5924NM</u>	Installation of RPM instrument.	Amended	06/03/1994
<u>SA5925NM</u>	Installation of oil pressure/temperature instrument.	Amended	06/03/1994
<u>SA7063NM</u>	Installation of acrylic window liners.	Amended	01/20/1999
<u>SA7155SW-D</u>	Installation of S-TEC System 65 two axis automatic flight guidance system, Model ST-420.	Amended	04/09/1996
<u>SA71GL (1 OF 3)</u>	Installation of air filters per AML No. SA71GL latest FAA approved revision on single-engine	Reissued	06/20/2000
<u>SA71GL (2 OF 3)</u>	Installation of air filters per AML No. SA71GL dated April 17, 1995 or latest FAA approved	Reissued	06/20/2000
<u>SA771GL</u>	Install nose gear shimmey dampener, P/N 1001, to replace Gerdes P/N A135-8.	Amended	09/12/1997
<u>SA7801SW-D</u>	Installation of S-TEC manual electric trim system.	Issued	07/16/1991
<u>SA8521SW-D</u>	Installation of a Century Automatic Flight System, Model YK1044 consisting of a Century yaw damper.	Issued	03/31/2000
<u>SA8534SW-D</u>	Installation of a Century Automatic Flight System, Model AK1056.	Amended	03/13/2003
<u>ST01085LA (2 OF 2)</u>	Installation of the VNS 1000 Voice Navigation System.	Amended	02/26/2001
<u>ST01700NY (1 OF 2)</u>	Installation of the following Aerospace Logic aircraft instruments: EGT-100 Exhaust Gas Temperature	Issued	07/08/2003
<u>ST02547AT (2 OF 2)</u>	Installation of a voice alert system.	Amended	05/13/2003

Commander 114B

<u>SA00402SE</u>	Installation of a remote spin-on oil filter adapter. (GC-1B w/Lycoming or Cont 360 engine	Amended	04/24/2000
<u>SA00432SE</u>	Installation of EGT 701 series fuel flow instrument.	Amended	04/19/2002
<u>SA00556WI</u>	Installation of a functioning TKS ice protection system.	Amended	04/27/1998
<u>SA00769CH</u>	Authorizes installation of engines equipped with Unison Limited Authority Spark Advance Regular	Issued	10/21/1997
<u>SA00817WI-D</u>	Installation of Bendix/King KFC 225 Automatic flight Control System.	Reissued	02/28/2000
<u>SA00847WI</u>	Installation of a dual/single Garbin GNS 430 GPS/COM/NAV System.	Issued	01/03/2000
<u>SA00861SE</u>	Installation of J.P. Instruments (JPI) fuel flow indicating system in accordance with JPI	Issued	12/18/2000
<u>SA00865SE</u>	Installation of vortex generators on the wings, horizontal tail surfaces and vertical fin.	Issued	01/09/2001
<u>SA00893WI</u>	Installation of a Garmin GNS 530 VHF COM/NAV/GPS system.	Issued	07/28/2000
<u>SA00929WI</u>	Installation of Garmin Model GTX 327 transponder.	Issued	12/01/2000
<u>SA00954SE (2 OF 2)</u>	Installation of J.P. Instruments (JPI) Primary Temperature Indicating System in accordance with JPI	Amended	08/11/2003
<u>SA01105WI-D (2 OF 2)</u>	Installation of Bendix/King KMD 550/850 Multi-Functional Display System with optional traffic,	Issued	08/16/2002
<u>SA01229SE (1 OF 4)</u>	Installation of CNX80 GPS WAAS Navigator with integrated VHF Navigation and Communication radios.	Issued	06/27/2003
<u>SA02154AK</u>	Installation of the UPS Aviation Technologies, Inc, Apollo MX20 multi-function display, P/N	Reissued	10/14/2003
<u>SA02203AK (1 OF 3)</u>	Installation of FlightLogic Synthetic Vision Electronic Flight Information System (EFIS-SV).	Issued	03/26/2003
<u>SA02532AT</u>	Installation of subject Michelin tires on appropriate aircraft. For Michelin 5, 6, 8, and 10-inch	Issued	06/05/2002
<u>SA09470SC</u>	Installation of Starter Indicator light system.	Issued	06/18/2001
<u>SA1229CE</u>	Installation of King KFC-200, 2 axis(3 optional) flight control system with KCS 55/55A compass and	Reissued	02/28/2000
<u>SA2677CE</u>	Installation of aileron and flap gap seals.	Amended	07/30/2003
<u>SA4005NM</u>	Installation of Precise Pulselite control unit in landing/taxi system. (HP Jetstream Model 3101 AND	Amended	06/04/2001
<u>SA4172NM</u>	Installation of Aviation Development oil filter.	Amended	09/01/1999
<u>SA593CH</u>	Install Unison SlickSTART tm magneto booster system.	Amended	04/20/2000
<u>SA771GL</u>	Install nose gear shimmey dampener, P/N 1001, to replace Gerdes P/N A135-8.	Amended	09/12/1997
<u>SA7816SW-D</u>	Installation of S-TEC System 65 two axis automatic flight guidance system, Model ST-481.	Issued	06/25/1992
<u>SA7817SW-D</u>	Installation of S-TEC yaw damper system, Model ST-482.	Amended	08/09/1995
<u>SA7820SW-D</u>	Installation of System 40/50 single and two axis automatic flight guidance systems, Model	Issued	06/26/1992
<u>SA7822SW-D</u>	Installation of System 60 two axis automatic flight guidance system, Model ST-496, with optional	Issued	07/20/1992
<u>SA7823SW-D</u>	Installation of S-TEC manual electric trim system, Model ST-497.	Issued	07/21/1992
<u>SA8384SW-D</u>	Installation of S-TEC System 55/55X Two Axis automatic flight guidance system, Model ST-527, with	Amended	10/31/2001
<u>ST01085LA (2)</u>	Installation of the VNS 1000 Voice Navigation System.	Amended	02/26/2001

OF 2)

<u>ST01700NY</u>	Installation of the following Aerospace Logic aircraft instruments:	Issued	07/08/2003
<u>(1 OF 2)</u>	EGT-100 Exhaust Gas Temperature		
<u>ST02547AT (2)</u>	Installation of a voice alert system.	Amended	05/13/2003
<u>OF 2)</u>			

Commander 114TC

<u>SA00249WI-D</u>	Installation of Bendix/King KFC 200 Automatic Flight Control System. For serial numbers 20003,	Reissued	02/28/2000
<u>SA00402SE</u>	Installation of a remote spin-on oil filter adapter. (GC-1B w/Lycoming or Cont 360 engine	Amended	04/24/2000
<u>SA00432SE</u>	Installation of EGT 701 series fuel flow instrument.	Amended	04/19/2002
<u>SA00556WI</u>	Installation of a functioning TKS ice protection system.	Amended	04/27/1998
<u>SA00817WI-D</u>	Installation of Bendix/King KFC 225 Automatic flight Control System.	Reissued	02/28/2000
<u>SA00847WI</u>	Installation of a dual/single Garbin GNS 430 GPS/COM/NAV System.	Issued	01/03/2000
<u>SA00861SE</u>	Installation of J.P. Instruments (JPI) fuel flow indicating system in accordance with JPI	Issued	12/18/2000
<u>SA00865SE</u>	Installation of vortex generators on the wings, horizontal tail surfaces and vertical fin.	Issued	01/09/2001
<u>SA00893WI</u>	Installation of a Garmin GNS 530 VHF COM/NAV/GPS system.	Issued	07/28/2000
<u>SA00929WI</u>	Installation of Garmin Model GTX 327 transponder.	Issued	12/01/2000
<u>SA00954SE (2 OF 2)</u>	Installation of J.P. Instruments (JPI) Primary Temperature Indicating System in accordance with JPI	Amended	08/11/2003
<u>SA01105WI-D (2 OF 2)</u>	Installation of Bendix/King KMD 550/850 Multi-Functional Display System with optional traffic,	Issued	08/16/2002
<u>SA01229SE (1 OF 4)</u>	Installation of CNX80 GPS WAAS Navigator with integrated VHF Navigation and Communication radios.	Issued	06/27/2003
<u>SA02154AK</u>	Installation of the UPS Aviation Technologies, Inc, Apollo MX20 multi-function display, P/N	Reissued	10/14/2003
<u>SA02203AK (1 OF 3)</u>	Installation of FlightLogic Synthetic Vision Electronic Flight Information System (EFIS-SV).	Issued	03/26/2003
<u>SA02532AT</u>	Installation of subject Michelin tires on appropriate aircraft. For Michelin 5, 6, 8, and 10-inch	Issued	06/05/2002
<u>SA09470SC</u>	Installation of Starter Indicator light system.	Issued	06/18/2001
<u>SA2677CE</u>	Installation of aileron and flap gap seals.	Amended	07/30/2003
<u>SA4172NM</u>	Installation of Aviation Development oil filter.	Amended	09/01/1999
<u>SA593CH</u>	Install Unison SlickSTART tm magneto booster system.	Amended	04/20/2000
<u>SA7063NM</u>	Installation of acrylic window liners.	Amended	01/20/1999
<u>SA7817SW-D</u>	Installation of S-TEC yaw damper system, Model ST-482.	Amended	08/09/1995
<u>SA8384SW-D</u>	Installation of S-TEC System 55/55X Two Axis automatic flight guidance system, Model ST-527, with	Amended	10/31/2001
<u>ST01085LA (2 OF 2)</u>	Installation of the VNS 1000 Voice Navigation System.	Amended	02/26/2001
<u>ST01700NY (1 OF 2)</u>	Installation of the following Aerospace Logic aircraft instruments: EGT-100 Exhaust Gas Temperature	Issued	07/08/2003
<u>ST02547AT (2 OF 2)</u>	Installation of a voice alert system.	Amended	05/13/2003